UNCLASSIFIED

AD 419250

DEFENSE DOCUMENTATION CENTER

FOR

SCIENTIFIC AND TECHNICAL INFORMATION

CAMERON STATION, ALEXANDRIA. VIRGINIA



UNCLASSIFIED

NOTICE: When government or other drawings, specifications or other data are used for any purpose other than in connection with a definitely related government procurement operation, the U. S. Government thereby incurs no responsibility, nor any obligation whatsoever; and the fact that the Government may have formulated, furnished, or in any way supplied the said drawings, specifications, or other data is not to be regarded by implication or otherwise as in any manner licensing the holder or any other person or corporation, or conveying any rights or permission to manufacture, use or sell any patented invention that may in any way be related thereto.

FORWARDED BY THE CHIEF, BUREAU OF

PREPARED UNDER

BUREAU OF SHIPS

DEPARTMENT OF THE NAVY CONTRACT NO. NObs 86854

64-5

THERMOELECTRIC POWER CATALOGED BY **GENERATION**

QUALIFIED REQUESTERS MAY OBTAIN COPIES DE THIS REPORT FROM DDC.

A RESEARCH AND DEVELOPMENT PROGRAM ON MATERIALS AND **FABRICATION TECHNIQUES**

> QUARTERLY REPORT NO. 5 MAY 15, 1963

DIRECT ENERGY CONVERSION OPERATION

950 WESTERN AVE., LYNN: MASS.

RESEARCH AND DEVELOPMENT OF MATERIALS AND FABRICATION TECHNIQUES FOR THERMOELECTRIC POWER GENERATION

AUGUST 15, 1963

PREPARED UNDER BUREAU OF SHIPS
CONTRACT NUMBER NObs 86854
PROJECT SERIAL NUMBER SR-007-12-01 TASK 802

QUARTERLY PROGRESS REPORT NUMBER 5 JANUARY 1, 1963 - MAY 15, 1963

GENERAL ELECTRIC COMPANY DIRECT ENERGY CONVERSION OPERATION 950 WESTERN AVENUE, LYNN, MASSACHUSETTS

.

TABLE OF CONTENTS

			Page
INTRODUCTIO	ON		1
SUMMARY .			2
SECTION I -	CART	RIDGE DEVELOPMENT & EVALUATION	4
	I-1	Bonding Iron Diffusion Barriers	4
	I-2	Test & Evaluation	15
SECTION II -		MMENDATIONS FOR FUTURE CARTRIDGE CLOPMENT	20
	II-1	Improved Lead Telluride	20
	II-2	Minimization of End Constraints	21
	11-3	Ceramic Insulators & Seals	21

INTRODUCTION

This fifth quarterly report describes the cartridge development effort during the period January 1, 1963 to May 15, 1963 as funded by the Bureau of Ships under Contract NObs 86854.

Section I is a continuation of the cartridge fabrication and evaluation program. Section II is a summary of the effort accomplished to date and includes recommended future action.

SUMMARY

This report is intended to serve two purposes:

- To describe progress in cartridge development during this report period.
- 2. To summarize all effort to date and to recommend future action.

Attention has been focused upon the iron end cap bonding problem. The two techniques outlined in the previous report, namely, isostatic bonding and tin telluride brazing, have been explored in some detail. Results obtained with tin telluride brazing, although not conclusive, show low electrical resistance and the presence of inclusions in the vicinity of the bond. Temperature testing of elements with tin telluride brazed end caps has resulted in fractures in the "P" type element and in some cases separation from the iron end caps. The isostatic bonding of iron end caps has shown that low resistance joints may be obtained in this manner as measured in several of the specimens.

Before continuing with this development effort, the progress to date must be carefully reviewed. The majority of cartridges fabricated produced power initially but experienced degradation with time while in operation. There were no abrupt failures in power output which reflects favorably upon the electrical and mechanical integrity of the package. From the techniques explored in bonding iron diffusion barriers, hot pressing provided elements most nearly approaching design power output.

It is believed that a concentrated effort in improving the mechanical properties of PbTe and a provision for stress-free assemblies will provide a more reliable package for thermoelectric power generation.

SECTION 1 - CARTRIDGE DEVELOPMENT & EVALUATION

I-1 Bonding Iron Diffusion Barriers

The previous report described two approaches to the iron end cap bonding problem; namely, SnTe brazing and gas pressure bonding. The bonds obtained, although somewhat encouraging, did not entirely provide the desired results. Primary among the stated objectives was the requirement for a low resistance electrical interface between the diffusion barrier and the lead telluride elements which would also provide a mechanically sound bond when subjected to temperature cycling. Measurements clearly show that an r/p = 0.05 cm may be obtained, but the mechanical integrity of the bond during operation is questionable.

Gas Pressure Bonding of diffusion barriers has been attempted with autoclave facilities at Battelle Memorial Institute. A capsule method of material confinement resembling the thermoelectric cartridge represented the first attempt.

An examination of the capsules after processing indicated that some buckling in the sleeve had occurred. This was anticipated but to a lesser degree than had actually taken place. In a number of samples, cracks in the sleeve accompanied buckling and resulted in the leakage of PbTe through the container walls.

It is now believed that an extremely close fit between sleeve and

PbTe in the order of ± 0.001 inch with pre-indentations in the sleeve
to promote uniform buckling would have prevented mechanical failure.

Density measurements on material salvaged from the experiment show that theoretical single crystal density was nearly obtained in a number of the samples. In cases where no PbTe leakage took place, an apparent good bond between iron and lead telluride was obtained.

Measured values of the Seebeck coefficient and electrical resistance on a number of samples are tabulated below. It will be noted that there is considerable variation in these values from specimen to specimen indicating that they were not subjected to uniform heating in the autoclave.

Measurements of Seebeck Coefficient & Resistance
Isostatic Bonding - Battelle

	Specimen	Type	Seebeck Coefficient 	Resistance µn (over all)		
* 3	M (As Received)	P	64	525		
* 3	M (As Received)	N	152	650		
	#1	P	66	2075		
	#1A	P	83	3325		
**	#2 A	P	132	1675		
	#4	N	72	175		
**	#4A	N	87	317		
	#6	N	74	300		

^{*} Measured values of PbTe (1/2" D - 1/2" L) received from 3M for comparison with autoclave processed material.

^{**} Measurements performed by A. T. L. - G. E. Schenectady.


In the "N" type specimens, both the Seebeck coefficient and resistance decreased, indicating an increase in doping level. It is also believed that some excess lead was quenched into the lattice when the autoclave was cooled.


The "P" type specimens show higher Seebeck coefficients, indicating some loss of doping, and is indicated most noticeably in specimen 2A. Since the doping agent is sodium, it is possible that the doping loss was due to reaction with the mica sleeve which surrounds the PbTe billet. The high resistances are probably due to inclusions in the material or large voids in the vicinity of the iron end caps.


The resistances of specimens 4A and 2A were profiled, and plots of the results are shown in Figures 1, 2 and 3. For specimen 4A the results indicate little or no junction resistance, although an anomalous resistance point was obtained on the iron at one end of the specimen.

As the plot indicates, the resistivity of the material was fairly uniform, and approximately half as great as the resistivity of material not subjected to isostatic pressing.

In the first profile of specimen 2A (Figure #1, page 7), a resistance anomaly appeared in the center of the specimen. In this profile it was impossible to secure points on the iron end caps. The measurements were repeated along another track, and in the second profile (Figure 2, page 8) the end points refer to points on the iron.








The low resistance region in the center of the first plot was not found in the second and is believed due to an inclusion in the surface of the piece. Again, the bulk resistivity of the material appears to be uniform, but at this time on the curve it is higher rather than lower than the resistivity of the unpressed material.


In order to avoid buckling problems inherent in the original capsule approach, a flat plate with drilled holes for PbTe billet insertion will now be used for experimental purposes. Figures 4 and 5 on pages 11 and 12 show the material receiver plate and assembly with welded cover plates. After the assembly and welds are complete, air evacuation is effected by means of a pinch-off tube.

Extreme care will be exercised during assembly to remove surface oxides and in the selection of chemically compatible materials.

Unlike the original capsule technique where pressure was exerted on all exterior surfaces, pressure will now be applied to the ends of the elements only, with radial constraint provided by the material receiver walls.

In addition to bonding iron end caps to full cylindrical TE material elements, an attempt will be made to form P-N junctions and an assembled cartridge with the exception of the base seal.





It is believed that close control over process conditions will produce superior iron to telluride bonds without degradation in thermoelectric properties. Pressure will be held constant during the heating and cooling cycle to prevent the relaxation of elements in the assembly.

Tin Telluride Brazing studies have been conducted by the General Electric Advanced Technology Laboratory at Schenectady, New York, and at the Direct Energy Conversion Operation at Lynn, Mass. A brief summary of the results from these efforts follows.

The Tyco brazing technique was explored in detail with elements 1/4 inch in diameter and 1/4 inch long. Exploratory work with this geometry was conducted by A. T. L. Researchers there discovered that an initial r/p ratio of 0.06-0.05 cm could be obtained at operating temperatures. However, couple testing at design temperatures with temperature cycling resulted in the separation of the iron end caps from the SnTe.

A second attempt involving an improvement in material preparation to insure cleanliness and with temperature and time determined through experiment for the brazing operation resulted in what was believed to be the best possible bond. Again, couple operation at temperature with temperature cycling resulted in rapid degradation with each cycle. It is now believed that a systematic approach to the iron end cap bonding problem must involve an element geometry study to determine an acceptable length/area ratio and the evaluation of diffusion barriers which more closely match the coefficient of expansion of lead telluride.

Exploratory Tin Telluride brazing work at DECO has been restricted to the TE element geometries used in the cartridge (i.e. half cylinders with 1/2 inch diameter and a length of 1/4 inch). Again, almost negligible bond resistances were initially obtained with this technique. When these elements are fabricated into the cartridge and testing performed, rapid degradation accompanies temperature cycling.

A detailed examination of the failed cartridges has revealed that both iron end cap separation and cracks in the PbTe were responsible for the rapid degradation. This again clearly shows that coefficients of expansion between diffusion barriers and PbTe must be carefully matched.

Our continuing effort with SnTe brazing shall include an exploration of techniques to prevent iron end cap separation and that of lessening the stresses which result . element fracture.

I-2 Test and Evaluation

A total of 20 cartridges have been tested at the writing of this report. It is important to note that all units produced power initially and that there were no abrupt failures during operation at temperature. This would seem to indicate that when a fractured 'P' or "N" element is subjected to the compressive load, applied through differential expansion, the electrical integrity of the package is maintained.

Cartridges, during testing, have been subjected to the same conditions as in a generator application. Heat is applied with an exposed natural gas flame. Sink temperature is monitored and accurately controlled, with heat rejection to a water sink.

Tabulated data on Pages 16, 17 and 18 show electrical resistance during cartridge fabrication, maximum power obtained and information pertinent to fabrication and degradation. Cartridge degradation has resulted from corrosion within the package, fracture during operation, and separation of iron end caps from PbTe. We have shown that corrosion may be eliminated by providing an inert atmosphere (argon), through selection of materials for chemical compatibility and by a hermetically sealed enclosure. The bonding of diffusion barriers has received primary attention and is considered to be the paramount problem in the fabrication of the unit.

TABULATED DATA WITH COMMENTS PERTINENT TO CARTRUDGE FABRICATION AND TEST EVALUATION

COMMENTS	Compressed assembly including 17 mil iron end caps. Exhibited continuity and generated current when placed on a hot plate but failed when tested (with torch).	Pin hole developed in weld - 3 attempts failed to close it - sealed with water glass - no performance dats.	End cap weld interrupted welding on second try. Used in demonstration unit.	30 mil copper used to shim 'P' leg. End cap weld bubbled; no heat sink used, sealed with cement. Tested at A.T.L.	Copper shim under 'P' jeg. Base weld good, appearance fair, end weld very good. Thermocouple in hot junction to monitor temperature	The elements were washed thoroughly to remove flux and prevent corrosion. Welding was done in a bell far with an argon atmosphere. Performance - initially .71 W. cartridge-sink joint falled at 235 hours; after resoldering, P = .72 W. Therefore, initial power was higher. At 1000 hours P = .54 W; at 2000 hours and 50 thermal cycles, P = .40 W. Base welded twice, end cap OK on first try.	Fabricated same as \$6 except: (1) water glass on elements to prevent corrosion - N.G water glass flaked off. (2) sheet mics with a different binder used as insaltates - N.G the binder carbonised at operating temperature. Performance - 20 W insitially, .62 after 47 bours, 0+ at 167 bours. Silver shim on bot side shifted during assembly lawing poor contact and increased electrical and thermal impedance. Welded in bell jar, both welds OK on first try.	Solder joint washed thoroughly - 35 mil silver disc used as buffer at hot junction. Base weld OK, and weld OK on second try. Performance 89W initially, . 86 at 60 hours, degraded rapidly to 0+ after this. Thicker silver disc had sublimed quite a bit, increasing thermal impedance.	Both welds excellent on first try. Solder bridged elements at cold junction during sink attachment. Elements broke while disassembling to repair. No performance data.	• (Fixture motor burned out during first weld.) Circuit continuity check showed 90, resistance before test. Voltage but no current for first 20 minutes. Hot end insulator was off center 30 mile cassing the silver buffer to "cock." Although the base was flushed thoroughly after soldering, a beavy accumulation of rust was moticed at the cold end.
Max. Power (Watte)	•			. 65	82.	.72+	79 .	6		8 .
2 a a		•	~	×	-	-	-	~	-	•
No. of Welds East Ca		-	-	-	-	N	-	-	~	Ē
After		3000	3300 1200	2950 1125	2700 800	2975 1150	1450	3940 1560	4800	9500
tance (pm)								(before	500 (before 450 (splitting	\$00 (before 625 {spitting
Recietano After Bonding and Spiliting		1050 735	1035 750	809 605	970 495			500 4 50 1 50 1 150 150 150 150 150 150 150 150 150	0.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0	6 3
A A S S S S S S S S S S S S S S S S S S								a z	a. =	Q. Z.
ع.	11 0	a z	0. Z	4 2	4 Z	9 Z	9 Z		2	
1	•	. 500	. 500	. 500	. 500		. 500	. 500	. 500	. \$00
Cartridge No.	-	7	•	•	w	. - 16 -		•	•	01

TABULATED DATA WITH COMMENTS PERTINENT TO CARTRIDGE FABRICATION AND TEST EVALUATION

		COMMENTS	Two 5 mil silver discs used to bridge hot end as 35 mil silver seemed unsatisfactory (high yield and sublimation rate). This is the first cartridge weided in the Hydrovoid Box. Performance 99 initially with 14% degradation during 170 hours. From then used 1200 hours, The first two affected it but succeeding ones did not. There were 50 thermal cycles. The first two affected it but succeeding ones did not. Ten eycles imposed on the cartridge within 4 hours (after 1700 hours of life) did not affect the rate of degradation. Power at 2000 hours 60 W. Disassembly - Removal of hot sides assembly aboved very little oxide on the heat transfer surfaces. The silver was discolored (black) only near the edges, 50% of the area of the iron end cap had recained its original lasters, and the elements were discolored only at the cold end (due to the soldering operation). There was no trace of the red oxide usually found on the cold subjection. A 1/8° wide band of PDTe had condensed on the mics insulation. Since everything is in fairly good condition, the degradation rate of 1.4% per 100 hours over the last 1800 hours of life could be attributed to a continual hot junction temperature of 1250°E+ (see cartridge no. 18).	The hot side assembly was brased, the only contact joint in the stack-up was between the from and caps and the silver buffer. This cartridge went 2000 hours with a final power output of .32 watts. Before final assembly, the 'P' leg was chipped on both corners and had a large peripheral crack which explains a higher degradation rate than No. 11. Disassembly showed fracture of the P'.	This is the first cartridge to have sheet iron diffusion barriers brazed on with SnTe. A disc of iron was used as both diffusion barrier and hot junction. Performance - Thermal impedance initially was very high. Thermal impedance increased and electrical impedance was 1/2 its initial value. A black deposit had formed on the silver buffer increased was a factor of the formed on the silver buffer increased was said that board was still intact on the hot side as deliberate removal of the end caps caused the separation to occur in the PbTe. Only 20% of the 'N' cold junction was wetted by SnTe.	A pin hele developed in the end cap weld. Re-welding falled to close the hole so it was tested as is. Thermal impedance increased with time and output decreased. Being exposed to the atmosphere probably caused a material degradation.	Hot pressed powdered iron on 'P' leg, SnTe brased sheet iron on 'N' leg. Per- formance degradation - 12% the first 100 hours, 2% the second 100 hours, 6% per 100 hours ever the next 300 houre. At 500 hours, two 80°F overshoots in temperature within 30 hours. Performance decreased 10% over the next 100 hours and the rate increased so that power was 0.16 watts at 1000 hours.
	Max.	Power (Watte)	.	6 .	3.	ż.	20.0
	ş	3 3	N	-	N	~	~
	No. of Welds	Base	-	N	m	-	m
		After	2050	3850 950	10, 500}	1580 1280	925 1590
(vil) •:		Junction	_ # # #	= 1275 µm,		190	95
Resistance (m)	After	•,	At disassembly, the 'N' had resistance of 8700 μs, 'P' = 27,700 μs. The hot side end ap of the 'P' fall off (bonded pay of the 'P' fall off (bonded new cold end cap resistance only 4250 μs.	(after dissessmbly N = 1275 μη. P = 55, 100 μπ)	1060 780	1420	765 1320
		As Received	At disassembly, i resistance of 8700 km. The heap of the 'p' fell plus cold are the edge plus cold are cold are cold only 4250 km.	(after disassem P = 55, 100 μn)			
		a	ρ, Ζ	A Z	a z	A Z	a z
		Length	. 500	. 500	. 300	. 342	. 353
		Cartridge No.	=	21	ā	2	15

TABULATED DATA WITH COMMENTS PERTINENT TO CARTRIDGE FABRICATION AND TEST EVALUATION

	COMMENTS	SnTe brazed sheet iron on a 'P' type Trancoa leg, SnTe brazed sheet iron on 3M 'N' leg. After three hours of operation, higher temperatures were needed to maintain design voltage showing a shift in the hot side assembly. The silver buffer sublimed, reducing the cross-sectional area of the hot strap resulting in increased electrical impedance.		seal was not gast tight sitter operation. Solid iron hot strap/diffusion barrier. Solder did not "take" on first attempt; second stitempt caused 'P' leg resistance to double. This cartridge had thermocouples at the hot junction and at both cold junctions. Performance was very poor, current only 0.1 amp. When the hot junction was 1100°F, the cold junction was 306°F which was higher than expected. The O. G. V. was 0, 201 volts ws. the desirin O. G. V. of 0, 230 volts; the hot junction temperature had to be increased to 1268°F which caused cold junction temperature to become 340°F. Failure is attributed to severe cracking of the 'P' leg. Poor sink attachment caused high electrical/thermal impedance.		Solid iron hot strap/diffusion barrier, no buffers. A hole developed in the end cap weld; removed cap and welded new cap in place - holes still there (contaminated sleeve 7). Performance - Since initial output was only 0.62 watts and there were holes in the hot end, the cartridge was run less than two hours. Disassembly showed a large accumulation of rust on cold iron end caps equal to 70% of accumulation of cartridges run for longer periods. Therefore, the oxide must be due to oxygen entrapment at assembly rather than base seal leakage. The metallized surface of the beryllia insulator nearest the hot junction "disappeared."	Serrated ixon end caps on hot end. One section of one cap broken off (approximately 20% of area). Not assembled.	Silver hot strap. Hole in end cap weld; tried filling with braze but hole remained.	Split end cap, silver bridge. Sleeve and end cap were pickled in a solution of H ₂ O, nitric and hydrofluoric acids for pre-weld cleaning. This appears to alleviate welding problems. Financial surfaces were attached for diplay proposes. It was tested to all the proposes and the second statements are according to the second statement.
	Max. I Power (Watts)	8 .	1. 12	†	1.01	. 62			
	No. of Welds End		~	-	1	4		~	1
	į pu		m	pred	m	m		~	-
	After	1695	1090	(1) (2) 2100 (1) (2) 1325	1125	1475	1100 890	1620 810	1675
ice (Im)	Junction	280 55							
Resistance (m.)	After Bonding and Splitting	1300	096	960	1000	995	825 790	1265	1420 925
	A. Received			42.5 400	320	375			052
		Δz	a z	a z	a z	AZ	A Z	a z	A Z
	Length	. 289	. 232	7.	. 260	. 242	. 242	242.	. 270
	Cartridge No.	2	11	æ	61	02	21	2	23

It was believed that the isostatic bonding of iron end caps would provide TE material densification approaching that of a single crystal and thereby improve its resistance to fracture. Material processed initially in the autoclave was not suitable for fabrication in the cartridge due to the very high resistance in "P" type elements.

SECTION II - RECOMMENDATIONS FOR FUTURE CARTRIDGE DEVELOPMENT

The development effort described below is aimed at solving problems encountered in cartridge fabrication. Since the cartridge method of material containment is mechanically sound and offers distinct advantages over other assembly methods, it must be explored in greater detail with emphasis on principal problem areas. Problem areas requiring continued exploration are the mechanical behavior of lead telluride and the bonding of diffusion barriers having low electrical resistivity combined with good mechanical strength.

II-1 Improved Lead Telluride

Metallographic sections of commercial PbTe thermoelements always reveal the presence of numerous small voids, micro-cracks and segregated phases in the grain boundaries. Because of these defects, commercial lead telluride as it is presently manufactured is considerably more brittle than the ideal polycrystal would be.

A study must be conducted to investigate the behavior of the lead telluride whose crystalline state approaches that of an ideal polycrystal more nearly than that of currently available commercial materials. The most promising method for producing such material appears to be casting with ultrasonic agitation of the melt during freezing.

Isostatic bonding results to date have shown that densities nearly equal to theoretical single crystal density may be obtained with this technique. This effort should, therefore, be continued in an attempt to improve PbTe mechanical properties through increased densification.

II-2 Minimization of End Constraints

Methods of minimizing the stresses due to end constraints on PbTe elements will be explored in detail. The following approaches will be investigated:

- Iron end caps will be split by methods that will remove the constraints introduced by solid caps, either through dicing or fabricating the end caps from a tightly wound spiral of iron strip.
- Materials whose thermal coefficient of expansion matches that of PbTe shall be explored and tested.

II-3 Ceramic Insulators & Seals

The use of ceramic materials will be investigated in the following areas:

- 1. Hot side assembly.
- 2. Cold side seal.
- 3. Inside wall insulation.

The hot side assembly is relatively simple since there are no leads to press through the shell at the end of the cartridge. The program will consist in finding or developing a suitable high temperature insulating adhesive for bonding iron to the inconel cap. A satisfactory adhesive would greatly diminish the temperature gradient at the hot side and simplify the assembly procedure.

The cold side seal is complicated by the necessity for making high current lead connections at the end of the cartridge. Several approaches are being considered which offer promise, but all of them will depend on effecting a bond with material having good thermal conductivity.

Ceramic to metal seals are better in strength and electrical insulation than ceramic to glass seals. The ceramic to metal seal, however, is usually difficult and costly to make. Figure 6 represents a concept in combining ceramic to metal sealing with glass bonding. Several variations will be evaluated.

Figure 6

